

William Kingsley

111 East Proctor Rd
Center Rutland, VT 05736

Invoice

March 22, 2022

Invoice for
Scott Bojrab

Invoice #

RWBB

Due date

3/24/2022

Currency: USD

Description	Qty	Unit price	Total price
RoadWing Shock Intended to be installed on a Yamaha Road Star PICTURES - https://www.jrbk.net/rwbb	1	\$200.00	\$200.00

Subtotal **\$200.00**

Shipping & Insurance **\$20.00**

Total Due: **\$220.00**

I am very active on the Road Star Facebook groups (since 2019) and well known among the other veteran users and admins. I am also a Moderator on the [Road Star Clinic Facebook Group](#). In addition I have been selling on [eBay](#) since 1998 and have a 100% feedback rating. I have converted and sold over 40 RoadWings and other parts on the Road Star Facebook groups. I encourage you to search my name among the groups and you will find lots of posts and comments by me. I can supply references from previous Facebook clients if you like. **PayPal fees keep going up therefore I will no longer accept PayPal Goods and Services.** I stand behind my product and will supply what I have described. I am willing to provide support after the sale as well.

ACCEPTABLE FORMS OF PAYMENT

I prefer to request the money through these apps to ensure that you pay the right person.

PayPal Friends and Family - @ijrbk (ebay@jrbk.net)

Venmo - @ijrbk

Cash App - \$ijrbk

Money Order - Pay to William Kinglsey (address above)

NOTES:

The preload was installed on the Gen1 shock and spring that you sent me and came from a shock off a 2018 Gold Wing GL1800. The preload was tested upon receipt and works as it should. The shock and spring also perform as they should. The flange came from a Gen1 shock. I used a little WD-40 and a towel to clean it up while it was a part. It was pretty clean, just dusty.

I converted it to a Roadwing using the method described at this website (<https://www.jrbk.net/roadwing/roadwing-conversion/>). Here is a summary of what was done: A new mounting hole was drilled in the shock arm and the excess was cut off and filed. The original bushing was pressed out from the collar and a new bushing and washers was installed in the collar with parts from McMaster-Carr. I cleaned up the shock using Dawn dish soap and water. The shock may have some surface rust but there is no rot and it is fully intact.

It will take some elbow grease to install this on your Road Star. Details on how to mount this shock can be found at <https://www.jrbk.net/roadwing-install/>

TERMS:

USED - Tested and found to work as it should - All Sales Final - No Returns - No Refunds - Pictures of the actual shock you will receive can be viewed at the link above - Shipping & Insurance via USPS Priority Mail within two business days of receipt of cleared payment.